THE PORT AUTHORITY OF NEW YORK AND NEW JERSEY

M E M O R A N D U M

TO: Stephen Berger, Executive Director
FROM: Victor Strom
DATE: July 18, 1986
SUBJECT: ASBESTOS SURVEY AND ANALYSIS REPORT - WORLD TRADE CENTER COMPLEX
REFERENCE: Memo; V. Strom to S. Berger, dated 7/2/86, same subject
Memo; V. Strom to S. Berger, dated 7/11/86, same subject

COPY TO: N. Budeiri, R. Fagin, M.D., P. Falvey, R. Linn, G. Tozzoli, R. Monti, M. Marchese, M. O'Brien, J. Vanacore

This is an update to the memo's referenced above. The following is the list of areas that were bulk sampled and air sampled at the World Trade Center during the period July 10 - July 16, 1986:

Bulk Sampling

Location	Results	Remarks
Subgrade B1 Level (Mechanical Equipment Room) (Five World Trade Center)	Asbestos Found	Two samples out of fifty three taken were found to contain asbestos. The positive samples were obtained from fallout material and pipe insulation
Subgrade B1 Level (Four World Trade Center) (Couputer Cooling Room)	No Asbestos	Samples were taken from sprayed on insulation material
Subgrade B1 Level (Four World Trade Center) (Swiss Bank, Mechanical Equipment Room)	No Asbestos	Samples were taken from sprayed on and pipe insulation material
Subgrade B1 Level (Four World Trade Center) (Mechanical Equipment Room)	No Asbestos	Samples were taken from pipe insulation material
Subgrade B2 Level (Dataport) (Five World Trade Center)	Asbestos Found	Three samples out of sixty one taken were found to contain asbestos. The positive samples were obtained from cementitious, trowled-on insulation present on the concrete slab ceiling
5th Floor Core Areas (Two World Trade Center)	No Asbestos	Samples were taken from sprayed-on, and troweled-on insulation material
6th Floor Maintenance Platforms (One World Trade Center)	Asbestos Found	Twenty one samples out of twenty three were found to contain asbestos. These samples were obtained from fluffy, sprayed-on insulation on ceiling and beams

M 009501
PX-680

CONFIDENTIAL

ı Floor "orld Trade Center)	Asbestos Fouad	Five samples out of tweaty eight collected were fouad to coatain asbestos. The positive samples were collected from sprayed-oa material oa structural members
t Floor o World Trade Center)	No Asbestos	Samples were collected from sprayed-oa material oa structural members.
h Floor o World Trade Center)	No Asbestos	Samples were collected from sprayed-oa material oa structural members aad deckiag.
:h Floor /o World Trade Center)	Asbestos Fouad	Two samples out of tweaty seveа samples collected were fouad to coataia asbestos. The positive samples were collected from sprayed oa material oa structural members.
th Floor wo World Trade Center)	No Asbestos	Samples were collected from sprayed-oa material oa structural members
ad Floor wo World Trade Center)	No Asbestos	Samples were collected from sprayed-oa material oa structural members.
th Floor)ae World Trade Center)	Asbestos Fouad	Two samples out of sixty five collected were fouad to coataia asbestos. The positive samples were collected from cemeatitious aad sprayed-oa material oa structural members.
)th Floor)ae World Trade Center)	Asbestos Fouad	Oae sample out of thirty two collected were fouad to coataia asbestos. The positive sample was collected from sprayed oa material oa metal deckiag.
3th Floor Two World Trade Center)	No Asbestos	Samples were collected from sprayed-oa material oa structural members.

ir Samples

ocatioa	Results
th Floor Maiateaaace Platforms Oae World Trade Center)	Three samples were takea aad the results were well below the curreat Federal staadards.
ith Floor Maiateaaace Platforms Two World Trade Center)	Three samples were takea aad the results were well below the curreat Federal staadards.

The attached graphic shows the survey locatioas completed as of July 23, 1986.

Victor T. Strom, Director
Public Safety Departmeat

M 009500

Location	Results	Remarks
6th Floor Maintenance Platforms (Two World Trade Center)	Asbestos Found	All twenty two samples taken were found to contain asbestos. These samples were obtained from fluffy, sprayed-on insulation on ceiling and beams
9th Floor (Mechanical Equipment Room) (Four World Trade Center)	No Asbestos	Samples were taken from pipe, and sprayed-on insulation material
9th Floor (Mechanical Equipment Room (Five World Trade Center)	No Asbestos	Samples were taken from pipe, and sprayed-on insulation material
73rd Floor (Two World Trade Center)	No Asbestos	Samples were taken from sprayed-on and troweled-on insulation material
74th Floor (Two World Trade Center)	Asbestos Found	Seventeen samples out of fifty two taken were found to contain asbestos. These samples were obtained from structural beams, and joists
75th Floor MER (One World Trade Center)	Asbestos Found	Fifteen samples out of a total of eighty three taken were found to contain asbestos Three of these positive samples are from sprayed on insulation mateial six from pipe insulation material and six from fall out material
108th Floor (One World Trade Center) (Mechanical Equipment Rom)	No Asbestos	Samples were taken from structural steel members and pipe insulation material

Air Samples

Location	Results
75th Floor (One World Trade Center) (Mechanical Equipment Room)	Eight samples were taken and the results were well below the current Federal standards
108th Floor (Two World Trade Center) (Mechanical Equipment Room)	Eight samples were taken and the results were well below the current Federal standards

The attached graphic shows the survey locations completed as of July 16, 1986.

Victor T. Strom, Director
Public Safety Department

THE PORT AUTHORITY OF NEW YORK AND NEW JERSEY

M E M O R A N D U M

TO: Stephen Berger, Executive Director
FROM: Victor T. Strom
DATE: August 1, 1986
SUBJECT: ASBESTOS SURVEY AND ANALYSIS REPORT - WORLD TRADE CENTER

REFERENCE: Memo's; V. Strom to S. Berger, dated 7/2/86, 7/11/86, 7/18/86, 7/24/86, same subject

COPY TO: N. Budeiri, R. Fagin, M.D., P. Falvey, R. Linn, G. Tozzoli, R. Monti, M. Marchese, M. O'Brien, J. Vanacore

This is an update to the memo's referenced above. The following is the list of areas that were bulk sampled and air sampled at the World Trade Center during the period July 24 - July 30, 1986:

Bulk Sampling

Location	Results	Remarks
Elevator pits 1 and 2 (Two World Trade Center)	No asbestos	Samples were collected from column insulation and material fallout.
Elevator pits 3 and 4 (Two World Trade Center)	No asbestos	Samples were collected from column insulation.
Elevator pit 5 (Two World Trade Center)	No asbestos	Samples were collected from sprayed-on insulation on structural members.
Elevator pits 6 and 7 (Two World Trade Center)	No asbestos	Samples were collected from cementitious insulation on structral members.
Elevator pits 16 and 17 (Two World Trade Center)	No asbestos	Samples were collected from cementitious insulation onstructural members.
Elevator pits 18 and 19 (Two World Trade Center)	No asbestos	Samples were collected from sprayed-on and cementitious insulation on structural members.
Elevator pits 20 and 21 (Two World Trade Center)	No asbestos	Samples were collected from cementitious insulation on structural members.
Elevator pits 24 and 25 (Two World Trade Center)	Asbestos found	Two out of three samples collected were found to contain asbestos. The positive samples were collected from sprayed-on column insulation and material fallout.
Elevator pit 27 (Two World Trade Center)	No asbestos	Samples were collected from cementitious insulation on structural members and fallout.
Elevator pits 28 and 29 (Two World Trade Center)	Asbestos found	Two out of three samples collected were found to contain asbestos. The positive samples were collected from sprayed-on insulation on the column.

M 002005

Elevator pits 30 and 31 (Two World Trade Center)	Asbestos found	Four out of four samples collected were found to contain asbestos. The positive samples were collected from sprayed-on and cementitious insulation, and fallout material.
Elevator pit 32 (Two World Trade Center)	Asbestos found	One out of one sample collected was found to contain asbestos. The positive sample was collected from fallout material.
Elevator pit 33 (Two World Trade Center)	Asbestos found	One out of one sample collected was found to contain asbestos. The positive sample was collected from fallout material.
Elevator pits 34 and 35B (Two World Trade Center)	Asbestos found	One out of three samples collected were found to contain asbestos. The positive sample was collected from sprayed-on column insulation.
Elevator pit 36 (Two World Trade Center)	Asbestos found	One out of three samples collected were found to contain asbestos. The positive sample was collected from sprayed-on column insulation.
Elevator pits 37 and 38B (Two World Trade Center)	Asbestos found	Three out of three samples collected were found to contain asbestos. The positive samples were collected from sprayed-on and cementitious column insulation and fallout material.
Elevator pits 39 and 40B (Two World Trade Center)	Asbestos found	Two out of two samples collected were found to contain asbestos. The positive samples were collected from sprayed-on column insulation.
Elevator pit 41B (Two World Trade Center)	Asbestos found	One out of three samples collected were found to contain asbestos. The positive sample was collected from sprayed-on column insulation.
Elevator pit 42B (Two World Trade Center)	Asbestos found	Two out of three samples collected were found to contain asbestos. The positive samples were collected from sprayed-on column insulation and fallout material.
Elevator pits 43 and 44 (Two World Trade Center)	Asbestos found	Two out of three samples collected were found to contain asbestos. The positive samples were collected from sprayed-on column insulation and fallout.

34th Floor (One World Trade Center)	Asbestos found	Seven out of thirteen samples were collected were found to contain asbestos. The positive samples were collected from sprayed-on and cementitious beam insulation.
40th Floor (One World Trade Center)	Asbestos found	Twenty six samples out of fifty one collected were found to contain asbestos. The positive samples were collected from sprayed-on and cementitious beam insulation.
45th Floor (One World Trade Center)	Asbestos found	One sample out of twenty two collected was found to contain asbestos. The positive sample was collected from sprayed-on beam insulation.
46th Floor (One World Trade Center)	Asbestos found	One sample out of nineteen collected was found to contain asbestos. The positive sample was collected from sprayed-on beam insulation.
47th Floor (One World Trade Center)	No asbestos	Samples were collected from sprayed-on cementitious insulation on structural members.
'st Floor (One World Trade Center)	No asbestos	Samples were collected from sprayed-on and cementitious beam insulation.
54th Floor (One World Trade Center)	No asbestos	Samples were collected from sprayed-on and cementitious insulation on structural members.
61st Floor (One World Center)	Asbestos found	One sample out of twenty collected was found to contain asbestos. The positive sample was collected from sprayed-on joist insulation.
63rd Floor (One World Trade Center)	Asbestos found	One sample out of twenty collected was found to contain asbestos. The positive sample was collected from cementitious beam insulation.
65th Floor (One World Trade Center)	Asbestos found	One sample out of twenty collected was found to contain asbestos. The positive sample was collected from cementitious beam insulation.
68th Floor (One World Trade Center)	No asbestos	Samples were collected from sprayed-on and cementitious insulation on structural members.
9th Floor (One World Trade Center)	No asbestos	Samples were collected from sprayed-on and cementitious insulation on structural members.